



LEVITON



Line Hot/Ligne actif/Línea Fase



WARNING: TURN OFF POWER. TEST POWER IS OFF. TO BE INSTALLED AND/OR USED IN ACCORDANCE WITH APPROPRIATE ELECTRICAL CODES AND REGULATIONS.

To Side Wire: Terminal screws accept up to #10 AWG **copper or copper clad wire**. Remove wire insulation approx. 3/4" (1.9 cm). Connect wires per wiring diagram as follows: Loop wires clockwise 3/4 turn around terminal screws. Firmly tighten screws over wire loops.

AVERTISSEMENT : VÉRIFIER QUE L'ALIMENTATION SOIT BIEN COUPÉE. INSTALLER ET UTILISER CONFORMÉMENT AUX CODES DE L'ÉLECTRICITÉ EN VIGUEUR. COUPER L'ALIMENTATION.

CÂBLAGE LATÉRAL : Les bornes acceptent les fils de **cuivre ou plaqués cuivre** d'un calibre pouvant atteindre 10 AWG. Dénuder les fils sur un peu moins de 2 cm. Raccorder les fils conformément au SCHÉMA DE CÂBLAGE : enrouler les fils sur les bornes de trois quarts de tour vers la droite. Serrer fermement les vis sur les fils.

ADVERTENCIA: DESCONECTE LA CORRIENTE. PRUEBE QUE LA CORRIENTE ESTA DES-CONECTADA. PARA INSTALARSE Y/O USARSE DE ACUERDO CON LOS CODIGOS ELECTRICOS Y NORMAS APROPIADAS.

Para Cableado Lateral: Los tornillos terminales aceptan cable de **cobre o revestido de cobre** hasta #10 AWG. Quite 1.9 cm. (3/4") de aislante. Conecte los cables según el diagrama de cableado: Enrosque los alambres 3/4 de vuelta hacia la derecha alrededor de los tornillos terminales. Apriete los tornillos sobre el alambre enroscado.