

HOW TO USE:

1. Protect hands with chemical-resistant glove, and eyes with chemical splash goggles.
2. Shake well. Pour into a metal container and apply with a paintbrush.
3. After 30 minutes (up to 24 hours), scrape a small test area to see if the finish is ready for removal.
4. Use a paint stripper wash or Odorless Mineral Spirits with an abrasive stripping pad to loosen remaining residue. Surface should be completely clean and dry before refinishing.

