### For EPDM Membrane Roof or Hot Tar Roof


### Step 1:

Turn the vent upside down and make a cardboard template from the flange. The template should be the same size as the flange with the hole in the middle.




## Step 2:

Using the template, trace the square and circle onto the roof as shown.




### Step 3

Remove cardboard template, The square and circle pattern shown.



## Step 4:

With a razor blade, cut the circle traced out onto the membrane and remove. Then with a reciprocating saw, cut a hole in the roof deck and remove all debris.





# **Active Ventilation Products, Inc.**


311 First Street, Newburgh, NY 12550-4857

800-ROOF VENT (766-3836) Ph: 845-565-7770 Fax: 845-562-8963

 5778-7

### For EPDM Membrane Roof or Hot Tar Roof

**Step 5**: Apply sealant within the square flange outline.




Step 6:

Place vent within the square outline & attach using a screw gun or drill.



### Step 7:

Required screw: #10 x 1.5" steel sheet metal screw
Total number of screws required = **12** (tolerance : 1/2")



### Step 8:

Appy roofing cement over the screws and edge of flange. This is how the keepa vent should look when finished.





## **Active Ventilation Products, Inc.**

311 First Street, Newburgh, NY 12550-4857

800-ROOF VENT (766-3836) Ph: 845-565-7770 Fax: 845-562-8963

 5778-7