Care and Maintenance

1. Wipe with a soft dry cloth. Avoid the use of harsh chemicals and household cleaners as they may damage the finish.

2. Hardware may loosen over time; periodically check that all connections are tight.

3. Blot spills immediately with a clean, colorfast towel. Spot clean with a damp cloth or sponge, gently blotting to remove excess water, then air dry. For stains that can't be removed as such, professional cleaning is advised.