STOPS & PREVENTS LEAKS

FLEXIBLE

PAINTABLE

Pro Tips:

1. Shake well before use. Spray a slight amount away from body to purge nozzle. Spray can 8”-12”from surface for best, even coverage.
2. Keep can upright when spraying for an extended period
3. Apply multiple coats to ensure all cracks and holes have been filled. Allow to dry 15 minutes between coats
4. For best reusability, turn can upside down and spray a short jet of clear gas after completing the job.