FILLING INSTRUCTIONS

1. Wear safety goggles and gloves when filling the torch.
2. Use fuel canister when filling torch with fuel.
3. Torch must be extinguished before filling.
4. Torch must be cooled to room temperature before filling the torch.
5. Fill torch in a well-ventilated area free of fire or other sources of ignition and away from people.
6. Do not smoke while filling the torch.
7. Hold the torch upside down.
8. Invert the fuel canister and insert the fuel canister tip into the fill valve on the bottom of the torch.
9. Push the fuel canister and torch together to allow fuel to flow into the torch fuel tank.
10. Stop filing if the fuel begins to overflow.
11. After filling, allow fuel to stabilize 3 minutes before igniting the torch.
12. After filling, listen for leaks. Do not use if leaking.