



BEHR PREMIUM® Wood Stain & Finish Stripper No. 64-N

- Removes Existing Oil & Water-Based Stains and Finishes
- For Horizontal & Vertical Wood Surfaces
- Removes Sealers, Waterproofers and 100% Acrylic Stains
- Perfect for Wood Decks, Siding and Shingles



Coverage:
60-75 Sq. Ft.



Keep Surface Wet
During Use



Shake Well
Before Use



Soap & Water
Clean-Up

Removes loose wood fibers without sanding. Not for interior use or on aluminum surfaces. May harm bare metal or painted surfaces.

WHERE TO USE

- Exterior water-based, oil-based and 100% acrylic coatings on Wood Decks, Porches & Patios, Siding, Fences, Shakes and Shingles.

SURFACE PREPARATION† (Proper Surface Preparation is Required.)

- Be sure to have a source for water, hose with nozzle and stiff bristle broom or brush and a product such as BEHR PREMIUM® NO. 63 All-In-One Wood Cleaner.
- DO NOT THIN PRODUCT.
- Do not apply in direct sunlight or on hot surfaces.
- Dampen nearby foliage with water and cover with plastic drop cloths.
- **Wear protective clothing, goggles, acid resistant gloves, and NIOSH approved respirator.**
- Conduct a small test patch in an inconspicuous area to ensure product performance.
- Prevent all rinse solution from entering storm drains.

APPLICATION

- Use product when air and surface temperatures are between 40-90 F (5-32 C).
- Wear protective clothing, goggles, and acid resistant rubber gloves and boots. Use a NIOSH approved air purifying respirator with an organic vapor cartridge.
- Completely wet the entire wood surface then apply a thick layer of stripper onto the surface using a paint brush or a stiff bristle broom to spread evenly.
- Completely cover original coated surface.
- Allow product to stand for a minimum of 1 hour. More opaque / thicker coatings may require more time.

- Penetration varies according to coating type, thickness, and temperature. Check periodically to ensure that the coating has softened and is completely covered with the stripper. If the coated surface becomes dry, re-apply a light coating to dry areas. The stripper should remain wet and active until the coating softens.
- Use a stiff brush to scrub and remove all coating and residue. Some areas may require an additional application.
- Rinse thoroughly with water to remove all chemical residues before recoating. Allow surface to dry completely before recoating.
- Follow up with a product such as BEHR PREMIUM No. 63 All-In-One Wood Cleaner to remove stains and rejuvenate natural wood color.
- In case of contact with painted or finished surfaces, rinse immediately with fresh water. Product will damage automobile finishes.

DRY TIME

- Surfaces must be thoroughly dry before applying any type of new finish, except those finishes that can be applied to dampened wood.
- Allow the wood to dry for a minimum of 24 hours in warm, dry weather.

DISPOSAL

- Properly dispose of all soiled rags.
- To recycle or properly dispose of paint in your community, contact your household refuse collection service.
- **PROTECT FROM FREEZING.**

† **WARNING!** If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. Contact the National Lead Information Center at 1-800-424-LEAD or log on to www.epa.gov/lead.

WARNING! Sanding or scraping pressure treated lumber may be hazardous; wear appropriate protection.

LIMITED WARRANTY

Behr Process Corporation warrants that this product meets Behr's manufacturing specifications. If this product does not meet these specifications, Behr Process Corporation will, at its option and upon proof of purchase, either furnish an equivalent amount of new product to you or refund the purchase price of this product. **This warranty is made to the original residential product purchaser and is not transferable. This warranty excludes (1) labor and costs of labor for application or removal of any product or (2) any incidental or consequential damages, whether based upon breach of express or implied warranty, negligence, strict liability or any other legal theory.** Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.

To consult with a Behr Certified Coatings Professional, call 1-800-854-0133 (U.S.A. only).

DANGER. CAUSES SEVERE EYE DAMAGE. CAUSES SKIN IRRITATION. MAY CAUSE AN ALLERGIC REACTION UPON SKIN CONTACT. CONTAINS: BENZYL ALCOHOL, GLYCOLIC ACID, DISTILLATES (PETROLEUM), AND POTASSIUM PYROPHOSPHATE. USE ONLY WITH ADEQUATE VENTILATION. NOTICE: Do not mix BEHR PREMIUM NO.64 Wood Stain & Finish Stripper with chlorine bleach or with any other household or industrial cleaning product or detergent. Mix only in plastic containers. Use in areas with adequate ventilation. Avoid contact with skin and eyes. Avoid breathing mist and vapors. Wear protective clothing and eye protection. Wash contaminated clothing before reuse. Close container after each use. **FIRST AID:** If on skin, remove contaminated clothing and rinse skin with water. Seek medical attention. If in eyes, rinse continuously with water for 20 minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If swallowed, do not induce vomiting. Get medical attention immediately.

KEEP OUT OF REACH OF CHILDREN – DO NOT TAKE INTERNALLY.



©2025 BEHR Process LLC
Santa Ana, CA 92705 U.S.A. • behr.com
V.O.C. (C.O.V.) 40.9 WT. % • REV. 4/25