

DRYING: ZAR® Poly Crystal Clear dries to the touch in 30 minutes, and can be recoated after 2 hours. Drying time will be affected by temperature, humidity, and film thickness. If while sanding, sandpaper gums or surface feels tacky, extend drying time.

CLEAN UP: Clean brushes and tools immediately after use with warm soapy water.

COVERAGE: Covers up to 125-150 sq. ft. (11.6 m²-13.9 m²) per quart.

Caution: Keep away from heat and flame.

Use only with adequate ventilation. Ensure fresh air entry during application and drying. If you experience eye watering, headache, or dizziness, or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH-approved) during and after application. Follow respirator manufacturer's directions for respirator use. Wash thoroughly after handling.

KEEP OUT OF REACH OF CHILDREN.

FIRST AID: If you experience difficulty in breathing leave the area to obtain fresh air. If continued difficulty is experienced, call poison control center, hospital emergency room or physician immediately.

If spilled, contain spilled material and remove with inert absorbent. Dispose of contaminated absorbent, container, and unused contents in accordance with local, state, and federal regulations.

KEEP FROM FREEZING.

 **WARNING:** Cancer and Reproductive Harm – www.P65Warnings.ca.gov.



DOES NOT EXCEED MAXIMUM VOC 275 g/L

UNITED GILSONITE LABORATORIES, 1396 Jefferson Ave., Dunmore, PA 18509
www.UGL.com

Order No. 32512

LR1219



INTERIOR WATER BASE

PREMIUM FINISHES

ZAR®

Poly

CRYSTAL CLEAR

HARD PROTECTIVE FINISH

Superior Scratch Resistance



1 QT (946 mL)
SEE CAUTIONS ON BACK LABEL

WARNING!
HARMFUL IF INHALED.

ZAR® Poly CRYSTAL CLEAR is a non-yellowing, water base, polyurethane specially formulated to protect and beautify cabinets, furniture, woodwork, and floors. It's self-leveling for a smooth finish and is ideal for use over light colored stains and paints. This fast drying, low-odor formula resists most household cleaners and abrasions. **Exotic hardwood approved – Ideal for use on Teak, Brazilian Walnut, and other exotic wood species.**

PREPARE WOOD FOR FINISHING

New Wood: Sand smooth using fine sandpaper, vacuum sanding dust. Wipe using a tack cloth to remove any remnants of dust before application. **Do not use steel wool.** Fill open-grained woods with ZAR® Wood Patch.

Old Clear Finishes in Good Condition: Remove grease, dirt, and wax. Sand lightly in the direction of the grain to remove any gloss. **Do not use steel wool.** Vacuum all sanding dust. Wipe using a tack cloth to remove any remnants of dust before application. If the old finish contains wax, regardless of condition, remove completely. Test ZAR® Poly Crystal Clear in an inconspicuous area for compatibility.

Old Clear Finishes in Poor Condition, Lacquer, or Shellac: Remove completely. **Do not use steel wool.** Sand and vacuum all sanding dust. Wipe using a tack cloth to remove any remnants of dust before application.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. **LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE.** Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

If wood is to be stained, use ZAR® Stain and allow to dry a minimum of 24 hours before top coating. For water base stains or oil base wood stains other than ZAR®, and follow manufacturer's drying directions.

APPLICATION: Apply when air and surface temperatures are between 60°F (15.5°C) and 90°F (32°C) and the relative humidity is less than 60%. Stir thoroughly before and during application. **DO NOT THIN.** Do not shake! Use a clean synthetic fiber or foam brush, synthetic applicator pad, or spray. Do not apply with a roller as it will create bubbles. To ensure satisfactory results, always test ZAR® Poly Crystal Clear in an inconspicuous area before completing the entire job. Apply thin coats at a rate of 125-150 sq. ft. (11.6 m²-13.9 m²) per quart in the direction of the grain. Thick coats may appear milky when dry. Do not over brush or trap air bubbles in the finish. Apply a second coat for maximum protection.

FLOOR APPLICATION: A minimum of three coats is required. Allow floors to dry 24 hours before subjecting to light foot traffic; 3-5 days before moderate (normal) traffic or moving furniture. To avoid marring floor, lift and place furniture. One week is required before maximum hardness is achieved. Do not cover floors with rugs before one week has elapsed. If floor should become marred or scratched, sand lightly using fine sandpaper, vacuum all sanding dust, wipe with a cloth dampened with water and apply another coat.