























ASSEMBLY INSTRUCTION FOR RX-D1297


	1  2PCS	2  1PC	
	3  1PC	4  1PC	
5  1PC	6  1PC	7  1PC	
8  1PC	9  1PC	10  1PC	11  1PC
12  2PCS	13  2PCS	14  1PC	15  1PC
16  1PC	17  1PC	18  1PC	19  1PC
20  1PC	21  2SETS	22  4PCS	

ASSEMBLY INSTRUCTION FOR RX-D1297


No.	PICTURE	SIZE	QTY
A		M6x35	27
B		Ø8x30	11
C		ST5x40	4
D		M6x30	2
E		M6x35	10

No.	PICTURE	SIZE	QTY
F		M6x50	2
G		ST3. 5x40	10
H		ST3. 5x14	16
			

STEP1




STEP2



ASSEMBLY INSTRUCTION FOR RX-D1297

STEP3




H



ST3.5x14

4

STEP4




A2



M6x35

8


B



Ø8x30

6

STEP5




A2



M6x35

10

B




Ø8x30

4


ASSEMBLY INSTRUCTION FOR RX-D1297

STEP6




C  ST5x40 2

STEP7



A1  $\phi 15$ 4


STEP8



A1  $\phi 15$ 4

ASSEMBLY INSTRUCTION FOR RX-D1297

STEP9




A



φ15

2

STEP10



A



φ15

8


C



ST5x40

2

STEP11



E






M6x35

10


ASSEMBLY INSTRUCTION FOR RX-D1297


STEP12




D  M6x30 2 **F**  M6x50 2

STEP13



A2  M6x35 9 **B**  ø8x30 1 **A1**  ø15 5


STEP14




G  ST3. 5x40 6

ASSEMBLY INSTRUCTION FOR RX-D1297

STEP15



G



ST3. 5x40

4


A1



Ø15

4

STEP16



21B

H



ST3. 5x14

8

STEP17

