




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 52129,52229,52329,52429
JONES SWIVEL STOOL



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)




847-949-6300
877-267-2261




customerservice@
boraamindustries.com




www.boraamindustries.com




M6x10:22 PCS




M6x13:2 PCS




M6x16:26 PCS




Ø7.5x15.5:2 PCS




M6x35:4 PCS




M6x40:12 PCS




M6x45:6 PCS



M6x50:2 PCS




M6x60:4 PCS




Allen Wrench:1 PC


1




2




3




4




5








6



7






01



DO NOT TIGHTEN BOLT COMPLETELY.




02

A  6 PCS	C  6 PCS	G  2 PCS	I  4 PCS
---	---	---	---






TIGHTEN BOLT COMPLETELY.


03




TIGHTEN BOLT COMPLETELY.

04

A 	B 	C 	D 	G 	H 
2 PCS	2 PCS	2 PCS	2 PCS	4 PCS	2 PCS



TIGHTEN BOLT COMPLETELY.



BE SURE TO CHECK ALL BOLTS ARE SECURELY
TIGHTENED PRIOR USING THIS STOOL.