BEHR PREMIUM®

SPRAY PAINT

BEHR PREMIUM® Spray Paint features an enhanced formulation that combines paint and primer◊ in a single can, delivering a premium, durable finish. Designed for both indoor and outdoor projects, BEHR PREMIUM Spray Paint can be used on wood, metal, plastic, cast stone and wicker. Weather and corrosion resistant, it delivers a reliable, long-lasting finish.

◊A primer coat may be needed on some surface.

Ideal for use on properly prepared surfaces such as:

• Wood • Metal • Plastic • Cast Stone • Wicker

CONTAINER CAP PROVIDES CLOSE APPROXIMATION OF COLOR AND SHEEN OF THE PRODUCT.

PRODUCT SPECIFICATIONS

Colors:

B000144	Black Gloss
B000244	Orion Gray Gloss
B000344	Lunar Surface Gloss
B000444	Hidden Sea Glass Gloss
B000544	Inked Gloss
B000744	Baronial Brown Gloss
B000844	No More Drama Gloss
B000944	Flirt Alert Gloss
B001044	Unmellow Yellow Gloss
B001144	Luck of the Irish Gloss
B001244	Congo Gloss
B001944	White Gloss
B002044	White Matte
B002144	Black Matte
B002944	Iron Mountain Satin
B003144	Citrus Orange Gloss
B005644	Tree Top Green Gloss
B006344	Dark Truffle Flat
B006844	Black Satin
B006944	White Satin
B007244	Deep Espresso Satin
B007644	Ocean Abyss Gloss
B007844	Summer Sun Flat
B007944	Desert Coral Flat
B009344	Sugary Pink Gloss
B009444	Blue Bandana Gloss
B009544	Royal Purple Gloss
B009644	Black Semi-Gloss
B009744	White Semi-Gloss

Finish:

Flat: < 5 @ 60°
Satin: 20–30 @ 60°
Gloss: > 80 @ 60°

Sheen may be affected by texture, porosity of the surface, and atmospheric conditions.

Resin Type: Modified Alkyd

Net Weight: 12 oz / 340 g

***% Solids by Volume:** 17% ± 2%

***% Solids by Weight:** 28% ± 2%

Max Product-Weighted MIR:

Flat: 0.80
Non-Flat: 0.95

Coverage: 10–15 sq ft per can, depending on the surface texture, porosity and application method. Does not include the loss of material from spraying.

APPLICATION

- Shake can vigorously for 1 minute after mixing ball begins to rattle and often during use.
- Test your spray application technique on a scrap surface or inconspicuous area before starting the project.
- Hold can upright, moving from side-to-side while spraying lightly and evenly about 12" from area being painted. Always start and finish spraying off the object. Each spray pass should overlap the previous pass by half.
- Apply multiple thin coats to prevent dripping and sagging. Allow to dry between each coat.

Dry Time: @ 77°F & 50% RH:

To Touch: 15 minutes
Re-coat: Within one hour or after 24 hours

Dry times are temperature, humidity, and film thickness dependent.

SURFACE PREPARATION

- The surface must be clean, free of dust, grease, wax, peeling paint, mold and mildew. If washing is necessary, use a non-soapy detergent or a TSP substitute. Rinse well and allow to dry.
- Scrape off loose paint and sand to a smooth surface.
- For maximum adhesion, sand glossy surfaces thoroughly before coating.

Stain-Blocking:

- If stain-blocking performance is required, apply a coat of primer such as KILZ® ORIGINAL Interior/Exterior Oil-Based Aerosol Primer No. 1008.

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Center at 1-800-424-LEAD or log on to www.epa.gov/lead.

CLEAN-UP/DISPOSAL

- Clear spray valve immediately after use by turning can upside down and spraying until only clear gas is released. If spray nozzle becomes clogged, remove and clean with paint thinner or mineral spirits where allowed.
- Do not stick pins or wire into the can valve opening.
- Clean fresh overspray with VOC-compliant paint thinner or mineral spirits. Otherwise use acetone. Remove dried paint with paint remover, but test small area first to ensure paint remover does not damage substrate.
- Wipe off tip before storing.
- Do not burn or place in home trash compactor.
- For recycling or disposal information, contact your household refuse collection service.
- Shelf life under normal conditions is two years unopened.

CAUTIONS/LIMITATIONS

- For best results, apply when air, material and surface temperatures are between 50°F and 90°F. Avoid painting in direct sunlight. Temperature and humidity extremes can affect dry time and final appearance.
- Avoid spraying in very windy and dusty conditions.
- Ensure adequate ventilation when spraying indoors.
- Cover adjacent areas to avoid overspray.
- Do not apply directly to galvanized steel without first applying a metal primer.
- Not for touch-up on surfaces previously painted with non-aerosol BEHR paint.

All trademarks, service marks, trade names, and trade dress appearing on this document are the property of their respective owners.
*Values given here are from BEHR PREMIUM® Gloss White Spray Paint.

HEALTH & SAFETY INFORMATION

DANGER. EXTREMELY FLAMMABLE LIQUID AND VAPOR. VAPORS MAY CAUSE FLASH FIRE. VAPOR HARMFUL. CAUSES SERIOUS EYE DAMAGE. IRRITATES SKIN AND RESPIRATORY TRACT. VENTILATION REQUIRED: To avoid inhalation and combustion hazards (see below), DO NOT use this product unless you can achieve cross ventilation by opening windows and doors during application and drying. May affect the brain or nervous system causing dizziness, headache or nausea. **CAUSES SERIOUS EYE DAMAGE. IRRITATES SKIN, NOSE AND THROAT.** Do not breathe vapors or spray mist. If you experience eye watering, headaches or dizziness, increase fresh air, wear respiratory protection (NIOSH/MSHA TC 23C or equivalent) or leave the area. **VAPORS MAY IGNITE EXPLOSIVELY.** Do not spray near sparks, heat or open flame. Do not smoke. Vapors are heavier than air and can travel at floor level to distant ignition sources. Extinguish all flames and pilot lights and turn off stoves, heaters, electric motors, high intensity lights and other sources of ignition during use and until all vapors are gone. **WARNING-CONTENTS UNDER PRESSURE.** Do not puncture or incinerate container. Do not expose to heat or store at elevated temperatures above 120°F. Prolonged exposure to sun may cause bursting.

FIRST AID: If you have difficulty breathing, leave area to obtain fresh air. If difficulty continues, get medical attention immediately. If swallowed, call physician immediately. In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention. For skin contact, wash thoroughly with soap and water.

KEEP OUT OF REACH OF CHILDREN.

This information is provided "as is" and no representations or warranties, either expressed or implied, of merchantability, fitness for a particular purpose or of any other nature are made with respect to this information or to any product referred to in this information. For SDS or to consult with a Behr Paint Company Representative, call 1-800-854-0133 (U.S.A. only) or visit behr.com. ©2025 Behr Process LLC, Santa Ana, CA 92705 U.S.A.