




40" Plow Blade

For use on Yardmax Power Trackbarrow YD8105

Model #	YDB805
Length	40"
Height	20"
Weight	72.8 lbs



SUPPORT

Have questions about your YARDMAX equipment?
Call us at 847-327-0566 or 844-YARDMAX, email
us at support@yardmax.com, or contact us via your
favorite social media site.

ASSEMBLY

To assemble the plow blade follow the below instructions.

PLOW BLADE

1. Mount the mounting bracket to the blade using M8×30 hex bolts, washers and nuts. (See **Figure 1a**)




Figure 1a

	M8 × 30	× 4	1
--	---------	-----	----------

2. Position the pivot bracket inside the mounting bracket and align with mounting bracket holes. Secure with M20×95 hex bolt, washers and nut. (See **Figure 1b**)




Figure 1b

	M20 × 95	× 1	2
--	----------	-----	----------

3. Insert the shorter control lever into the longer lever. Align holes and fasten with M8×40 hex bolt, washers and nut. (See **Figure 1c**)




Figure 1c

	M8 × 40	× 1	3
--	---------	-----	----------

4. Attach control lever to the guide tube. Line up holes and fasten with M8×35 bolt, washers and nut.
5. Insert the handle grip into the holder.
6. Secure the support bracket into the control lever with pin 10×60 and bridge clip. (See **Figure 1d**)




Figure 1d

	M8 × 35	× 1	4
	10 × 60	× 1	
	2 × 11 × 35	× 1	

7. Install the mounting bracket base with two M10×30 bolts and washers. (See **Figure 1e**)





Figure 1e



8. Install the already assembled plow blade to the trackbarrow as shown. (See **Figure 1f**)






Figure 1f



PARTS DIAGRAM



PARTS LIST

No.	Description	Qty
1	Bolt M8×35	6
2	Shave Plate	1
3	Rubber Plate	1
4	Blade Weldment	1
5	Washer8	16
6	Nut M8	13
7	Landing Leg Weldment	2
8	Blade Fixed Bracket Weldment	1
9	Bolt M8×30	4
10	Bolt M20×95	1
11	Washer20	2
12	Nut M20	1
13	Blade Connecting Bracket Weldment	1
14	Bolt M12×40	4

No.	Description	Qty
15	Washer12	2
16	Washer12	3
17	Washer10	4
18	Washer10	4
19	Pin 10×60	1
20	Curved Support Bracket Weldment	1
21	Bolt M8×50	1
22	Active Connecting Weldment	1
23	Nut M12	2
24	Bolt M10×25	2
25	Bolt M8×35	1
26	Adjusting Rod Weldment B	1
27	Bolt M8×40	1
28	Adjusting Rod Weldment A	1

No.	Description	Qty
29	Handle Sleeve 28	2
30	Limiter Rod Wedment	1
31	Bolt M24×110	1
32	Limiter Weldment	1
33	Washer24	1
34	Lock Nut M24	1
35	Spring	1
36	Bridge Pin 2×11×35	1
37	Pin 4×40	1
38	Handle Grip 2	1
39	Bended Plate	1
40	Bolt M10×30	2
41	Handle Sleeve 25	1

Tame the Great Outdoors®

