U.S. Government

Federal law prohibits removal of this label before consumer purchase.

ENERGYGUIDE

Heat Pump
Cooling and Heating
Split System

TCL
Model TH18SVH22XWC

Cooling Efficiency Rating (SEER2)**

22.00 - 22.00

14.3
Least Efficient

42.0
Most Efficient

Range of Similar Models

** Seasonal Energy Efficiency Ratio 2

Heating Efficiency Rating (HSPF2)**

9.50 - 9.50

7.5
Least Efficient

14.6
Most Efficient

Range of Similar Models

** Heating Seasonal Performance Factor 2

▼ This system's efficiency ratings depend on the coil your contractor installs with this unit. The heating efficiency rating varies slightly in different geographic regions. Ask your contractor for details.

For energy cost info, visit
productinfo.energy.gov