

WHERE TO USE: FOR WOOD SUBSTRATES ONLY. Ideal for use on unfinished, interior wood surfaces, including floors, doors, trim, furniture, cabinets, and paneling.

COVERAGE: Approximately 600 sq. ft. (56 sq. meters) per U.S. gallon (3.78 L) depending on wood type, surface texture, and porosity. Coverage figures do not include material loss due to application or mixing.

SURFACE PREPARATION: Surface must be clean and dry. Remove all dust, dirt, grease, oils, wax, and any other surface contaminants. Previous coatings must be completely removed. Prepare bare wood for staining by sanding in the direction of the grain with sandpaper until smooth. Use a tack cloth or vacuum cleaner to remove any dust prior to staining.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust or fumes. LEAD IS TOXIC. EXPOSURE TO LEAD DUST OR FUMES CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a properly fitted, NIOSH-approved respirator and prevent skin contact to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the USEPA National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead. Follow these instructions to control exposure to other hazardous substances that may be released during surface preparation.

APPLICATION: Provide adequate ventilation. Different species of wood absorb stain differently. Test color on a hidden section or

scrap wood before staining a large area to determine the best time interval between application and wiping. Stir well before and during use. DO NOT THIN. When using more than one container of the same color, intermix to ensure color uniformity. Apply a uniform coat with a high-quality, natural bristle brush or a soft, lint-free cloth. Allow to penetrate 5 to 15 minutes, then wipe off excess stain with a soft, lint-free cloth. For increased depth of color, repeat stain application after 2 to 4 hours. Apply only when air, product, and surface temperatures are between 50°F (10°C) and 90°F (32°C). Protect with the appropriate water-based or solvent-based, clear topcoat after stain has dried thoroughly, 8 hours minimum.

DRYING: Dries to touch in 15 minutes and to handle in 30 minutes at 77°F (25°C) and 50% relative humidity. Allow a minimum of 8 hours drying before topcoating. To test for dryness, lightly rub with a white cloth. If the cloth picks up the color, wait at least one hour and retest. Drying times listed may vary depending on temperature, humidity, color, film build, air movement, and wood type.

CLEANUP: Clean all brushes and applicators with paint thinner or mineral spirits. **DANGER – RAGS, STEEL WOOL, OR WASTE SOAKED WITH OLYMPIC® STAIN MAY SPONTANEOUSLY CATCH FIRE IF IMPROPERLY DISCARDED. IMMEDIATELY AFTER EACH USE, PLACE RAGS, STEEL WOOL, OR WASTE IN A SEALED, WATER-FILLED, METAL CONTAINER.**

DISPOSAL: Contact your local environmental regulatory agency for guidance on disposal of unused product. Do not pour down a drain or storm sewer. U-7100-02

PRECAUTIONS AND FIRST AID: Inhalation of high concentrations of vapor may affect the central nervous system. Repeated exposure to high vapor concentrations may cause irritation of the respiratory system and permanent brain and nervous system damage. High vapor concentrations can cause headaches, dizziness, drowsiness and nausea and may lead to unconsciousness. Can enter lungs and cause damage. Keep away from heat, sparks and flame. Do not breathe vapor or mist. Do not swallow. Do not get on skin or clothing. Avoid contact with eyes. Keep container tightly closed and sealed until ready for use. Wash thoroughly after handling. Provide fresh air ventilation during and after application and drying. Avoid the inhalation of dust, particulates, spray or mist arising from the application of this preparation. Use personal protective equipment as required. **DANGER – RAGS, STEEL WOOL, OR WASTE SOAKED WITH OLYMPIC STAIN MAY SPONTANEOUSLY CATCH FIRE IF IMPROPERLY DISCARDED. IMMEDIATELY AFTER EACH USE, PLACE RAGS, STEEL WOOL, OR WASTE IN A SEALED, WATER-FILLED, METAL CONTAINER.**
FIRST AID: If swallowed, rinse mouth with water (only if the person is conscious). Call physician immediately. Do not induce vomiting unless directed to do so by medical personnel. If in eyes, rinse with water for 15 minutes. Check for and remove any contact lenses. In case of contact, immediately flush skin with plenty of water while removing contaminated clothing and shoes. Get medical attention if irritation develops. If inhaled, remove to fresh air. If experiencing respiratory symptoms call a POISON CENTER or doctor/physician. Contains: stoddard solvent (8052-41-3); alkyd resin (not available); linseed oil (8001-26-1); solvent naphtha (petroleum), medium aliph. (64742-88-7); lecithins (8002-43-5); 2-butanone oxime (96-29-7); fatty acids, C18-unsatd., dimers, reaction products with n,n-dimethyl-1,3-propanediamine and 1,3-propanediamine (162627-17-0); xylene (1330-20-7). Keep out of the reach of children. For workplace use, an SDS is available from your retailer or by calling (412) 492-5555. EMERGENCY SPILL INFORMATION: (412) 434-4515.