


**DIRECTIONS:** Turn all or disconnect power to unit being serviced. Shake well. Remove cap and point toward surface to be cleaned. Avoid spraying on electrical wires or connections. Thoroughly saturate the targeted area with product.



With this self-rinsing formula, the foam will break and condensation accumulation will completely rinse the emulsified material. **HOWEVER**, you may wipe clean or rinse with water if desired or if using on non-condensation producing coils. For extremely stubborn or heavy deposits, repeat application may be necessary. Turn on or return power to unit.