





















84C-097




REQUIRED TOOLS




	 A 4x		 B 2x	
	 B1 2x		 C 2x	
	 C1 2x		 D 4x	
	 E 6x		 F 2x	
	 F1 8x		 G 2x	
	 G1 4x		 G2 4x	
	 H1 4x		 H2 4x	
	 J 4x		 K 4x	
	 K1 4x		 L 1x	
	 M 1x		 N 4x	

3				
	N1 6x	P 4x	Q 2x	Q1 4x
				
	Q2 4x	R 2x	R1 4x	R2 4x
				
	S 4x	T 4x	U 112x	V 4x
				
	W 4x	W1 6x	Y 20x	Z1 12x
				
	S4 1x	1x		
	 M6x15 1 113x + 4	 M6x10 2 32x + 1	 M5x12 3 48x + 2	 ST4.8x12 4 24x + 2
	 5 2x	 8 12x		



<1>


A 4x




J 4x




3 12x M5x12







(B) 2x




(B1) 2x



(C) 2x



(C1) 2x




(P) 4x



(1) 42x M6x15

5

<2>







M6x10

2 32x

<3>



H1 4x




H2 4x




M5x12

3 32x

<4>



6



Technical drawing of an L-shaped angle, 100x100x10mm, with 4 holes. The drawing shows the profile of the angle with four circular holes, two on each leg, spaced 40mm apart and 10mm from the ends.





 3 4x M5x12



 4 ST4.8x12


 24x





<6>





(D) 4x



(L) 1x



(1) 12x M6x15









(E) 6x



(1) 18x M6x15

<7>





(M) 1x




(1) 1x M6x15



(5) 2x

<8>






F 2x



F1 8x



W 4x













W1 6x



1 30x M6x15








<9>







12

<10>








(R2) 4x






Y 16x




<12>







<13>

T 4x





S 4x








Z1 12x



8 12x

<14>



or

