



MATERIAL LIST


4 pc Machine Screw




T Handle (Included)



FOLDED POSITION FOR STORAGE



DO NOT REMOVE SCREW



UNFOLD CHAIR AND MAKE SURE LOWER
BACK SUPPORT IS IN THE FORWARD
POSITION FOR UPRIGHT ASSEMBLY

INSERT TWO MACHINE SCREWS ON EACH LEG