



Work bench with one drawer



1




- 1) M6x4.5 mm (x4)
- 2) M6x4.2 mm (x2)
- 3) M6x9.5 mm (x2)
- 4) M6x4.5 mm (x4)
- 5) (x4)
- 6) M6x7 (x1)
- 7) M6x10 (x1)
- 8) M6 (x7)
- 9) M6 (x2)
- 10) (x2)
- 11) (x1)
- 12) (x1)
- 13) (x1)

2




- A(x1)
- B(x1)
- C(x1)
- D(x1)
- E(x1)




- 14) (x2)
- 15) (x2)
- 16) (x1)
- 17) (x1)
- 18) (x1)
- 19) (x2)
- 20) (x1)

3




- 21) (x2)
- 22) (x2)
- 23) (x1)
- 24) (x1)
- 25) (x1)
- 26) (x1)


4




5



4)




5)




6)


6



4)




8)




9)


7



10)



11)




12)


8



13)




14)




15)


9



16)




17)



18)

10



11