
6898-10159 2-Tier Garment Rack @2019 Whitmor, Inc.







H 2 ea

G 2 ea Corner connector



1 2 ea Locking wheel



Middle connector


С	F10253
D	F10254
Е	F10252
F	F10249
G	F10255
Н	F10256
I	F10257
.l	F10258

F10250 F10251

Tools Needed: No tools required.

NOTE: Wheels should be inserted last.

STEP 1: Start by assembling the base. Insert two horizontal base tubes (E) into two bases (F).



STEP 2: Firmly insert bottom vertical tubes (A) into the base, make sure the pinholes are on top and facing each other.

STEP 3: Insert bottom hanging bar (D) into two middle connectors (H).


STEP 4: Place assembled hanging bar section on bottom vertical tubes (A).

STEP 5: Slide top vertical tube **(B)** through middle connectors **(H)** into the pinholes at the top of bottom vertical tubes (A). Align pinhead with the pinhole, press on pinhead and push until locked.

STEP 6: Insert top hanging bar (C) into the corner connectors (G).

STEP 7: Place assembled top horizontal bar section on tubes (B) and press down firmly.

STEP 8: Insert wheels (I) and (J) into bottom of base.



8680 Swinnea Road • Suite 103 • Southaven, MS • 38671

NEED HELP? For help with assembly, or if you are missing a part, please call Whitmor's Customer Service Department, 1-888-944-8667 between 8 a.m. and 4:30 p.m. (Central Standard Time) Monday through Friday. Or email: help@whitmor.com. Visit us online at www.whitmor.com

Rev. 0 | 1.15.19 Printed in Taiwan