



BEHR® ADVANCED FORMULA OIL-BASED WOOD STAIN

- For Both Horizontal & Vertical Surfaces
- Reduces Drips and Runs
- One-Coat Coverage
- Full-bodied stain for easy application and consistently beautiful results
- Ideal for both DIY and Pro users
- Also works on metal, fiberglass, and previously finished surfaces

No. B3500 Series

Available in a Tint Base and
Assorted Pre-tinted Colors



Prep Before Use



1 Coat Application
Additional Coats
if Desired



Spread Rate:
125 Sq. Ft. / Qt.



Clean-Up:
Mineral Spirits
or Paint Thinner

READY TO USE. PROTECT FROM FREEZING.

WHERE TO USE: Properly prepared interior wood surfaces, both previously finished and unfinished, painted surfaces, fiberglass, coated metal and composition surfaces. Excellent for both vertical and horizontal surfaces.

SURFACE PREPARATION* (For best results) 1. Surfaces (raw and previously finished) must be dry, clean, and free of dirt, grease and glue. 2. For Raw Wood: Sand with #120-grit sandpaper followed by #180-grit or finer for a smoother finish if desired. Remove all dust. 3. Over Previously Finished Surfaces: Lightly sand surface with a 400 grit sandpaper. Remove all dust. 4. To ensure uniform stain color and beautiful results on bare wood, apply BEHR Oil-Based Pre-Stain Wood Conditioner prior to staining. Follow label instructions.

PRODUCT PREPARATION AND COLOR TESTING Stir stain thoroughly before and occasionally during use. Do not thin. Always test stain on an inconspicuous area of the wood to verify desired color. Color will vary depending on type of wood. Work in a well-ventilated area.

STAIN APPLICATION ON BARE WOOD 1. After wood surface has been cleaned, sanded smooth and all dust removed, apply stain liberally in direction of grain with a brush, foam applicator or lint free cloth. 2. Allow stain to penetrate 5-10 minutes. 3. Wipe with a soft cloth, first across the grain, then with the grain until all excess is wiped off. 4. Do not allow stain that has not absorbed to dry on surface.

CLEAR FINISH APPLICATION 1. Allow stain to dry a minimum of 12 hours. Complete your project by applying a BEHR® clear protective finish, following label directions.

APPLICATION TECHNIQUES For application techniques on multiple substrates and decorative looks go to our how-to videos at www.behr.com

DRY TIME Allow at least 12 hours to dry before re-coating or top coating with a BEHR clear protective finish.

DISPOSAL For disposal of empty containers and unused product, contact your household refuse collection service.

LIMITED WARRANTY Visit behr.com/warranty or call 1-800-854-0133 Ext. 2 for more information.

***WARNING** If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. Contact the National Lead Information Center at 1-800-424-LEAD or log on to www.epa.gov/lead.

 **WARNING** Cancer and Reproductive Harm
www.P65Warnings.ca.gov

IMPORTANT STORAGE AND DISPOSAL: DANGER Rags, steel wool and waste soaked with *BEHR OIL-BASED WOOD STAIN may spontaneously catch fire if improperly discarded or stored. To avoid a spontaneous combustion fire, immediately after use, place rags, steel wool or waste in a sealed water-filled, metal container. Do not store unused product inside the home. For disposal guidance, contact your household refuse collection service, fire department, county or state government control agency.

DANGER HARMFUL OR FATAL IF SWALLOWED. COMBUSTIBLE LIQUID AND VAPOR. MAY CONTAIN: HYDROTREATED LIGHT DISTILLATES (PETROLEUM), NEPHELINE SYENITE, TITANIUM DIOXIDE, METHYL ETHYL KETOXIME, HEAVY ALKYLATE NAPHTHA (PETROLEUM), MEDIUM ALIPHATIC SOLVENT NAPHTHA (PETROLEUM), HYDROTREATED HEAVY DISTILLATES (PETROLEUM), STODDARD SOLVENT, CRYSTALLINE SILICA, ETHYLBENZENE AND CARBON BLACK. MAY AFFECT THE BRAIN OR NERVOUS SYSTEM CAUSING DIZZINESS, HEADACHE OR NAUSEA. CAUSES EYE, SKIN, NOSE AND THROAT IRRITATION. MAY CAUSE DAMAGE TO ORGANS THROUGH PROLONGED OR REPEATED CONTACT. NOTICE: Reports have associated repeated prolonged occupational exposure to solvents with permanent brain damage. Intentional misuse by deliberately concentrating and inhaling contents may be harmful or fatal. Keep away from heat and flame. Do not smoke. Prevent build-up vapors by opening all windows and doors to achieve cross-ventilation. Vapors are heavier than air, and can travel at floor level to distant ignition sources. Extinguish all flames and pilot lights and turn off stoves, heaters, electric motors, high intensity lights and other sources of ignition during use and until all vapors are gone. **USE ONLY WITH ADEQUATE VENTILATION.** To avoid breathing vapors and spray mist, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headaches or dizziness, increase fresh air. If properly used, a respirator (NIOSH-approved for organic vapor with P series particulate pre-filter) may offer additional protection; obtain professional advice before using. A dust mask does not provide protection against vapors. Avoid contact with eyes and skin. Wash thoroughly after handling. Close container after each use. **FIRST AID:** If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately. In case of eye contact, flush immediately with plenty of water for at least 20 minutes and get medical attention; for skin, wash thoroughly with soap and water. If swallowed do not induce vomiting. Call physician immediately.

KEEP OUT OF REACH OF CHILDREN-DO NOT TAKE INTERNALLY.

PLEASE SEE PRODUCT LABEL FOR SPECIFIC WARNINGS. WARNINGS MAY VARY BETWEEN PRODUCTS AND OR COLORS.



©2021 Behr Process Corporation
Santa Ana, CA 92705 U.S.A. • behr.com
V.O.C. (C.O.V.) <550 g/L • REV. 9/21