


Assembly Instructions




Plant Stand

Model No.
HOGA-JW0553
HOGA-JW0710

Contact Us




We're here to help you.



Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


Warm Tips

1. Carefully read these instructions and keep them for future reference.
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.




We recommend using hand tools for assembly.


If an electric screwdriver is used, reduce power and torque to avoid damage to the product.



Install the Anti-Tip Straps

Using the anti-tip straps can reduce the risk of tipping over, but can not eliminate it.














⚠ Caution




Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.




Parts List

1  1 pc	2  2 pcs	3  2 pcs	4  2 pcs
5  2 pcs	6  2 pcs	7  1 pc	8  1 pc
9  1 pc	10  1 pc	11  2 pcs	12  2 pcs
13  2 pcs	14  2 pcs	15  1 pc	16  1 pc

17  1 pc	18  1 pc	19  1 pc	20  1 pc
--	--	---	--


Hardware List

A	B	C	D
 M6x12mm 22 pcs+1pc	 M6x25mm 22 pcs+1pc	 M6x32mm 16 pcs+1pc	 M6x48mm 2 pcs+1pc

E	F	G	J
 2 pcs	 $\phi 7 \times 40 \text{mm}$ 4 pcs+1pc	 4 pcs	 10 pcs

K
 1 pc


1



B


M6x25mm
4 pcs

2



B	D
	
M6x25mm	M6x48mm
2 pcs	2 pcs



3



F


$\phi 7 \times 40 \text{ mm}$
4 pcs

4





A	C
	
M6x12mm	M6x32mm
4 pcs	4 pcs

5





G
4 pcs

6





A
M6x12mm
4 pcs

7



A	C
	
M6x12mm	M6x32mm
14 pcs	8 pcs


8






C

M6x32mm
4 pcs

9




10




B


M6x25mm
16 pcs



J
S
10 pcs



E
2 pcs



Thank you for your support!

