

Flexible Braided PVC Ice Maker Supply Line

1/4 in. O.D. Comp. x 1/4 in. O.D. Comp. x 5 ft.

CAUTION: DO NOT INSTALL THIS PRODUCT UNTIL YOU READ AND UNDERSTAND ALL INSTRUCTIONS. FAILURE TO FOLLOW THESE INSTRUCTIONS MAY RESULT IN PERSONAL INJURY, PROPERTY DAMAGE OR PRODUCT FAILURE.

The 1/4 IN. O.D. Compression x 1/4 IN. O.D. Compression x 5 ft. Flexible Braided PVC Ice Maker Supply Line by Apollo is a highly flexible water connector. Designed for longer life under harsh conditions, Apollo appliance connectors are corrosion resistant, highly flexible, extremely reliable water connectors.

FEATURES:

- Corrosion resistant
- Bends freely without kinking or crimping
- Quick & easy installation
- Washers included

INSTALLATION INSTRUCTIONS:

1. Shut off water supply at valve.
2. Thread one end of connector onto compression threads on the appliance.* Hand tighten, then wrench tighten 1/4 turn more.
3. Thread other end of connector onto the water supply stop outlet.* Hand tighten, then wrench tighten 1/4 turn more.
4. Turn on water supply and check for leaks. If any appear, carefully tighten nuts further. Tools Needed for Installation: Wrench

**NOTE: Connector includes washers, DO NOT USE THREAD SEALANT. To prevent premature wear and connector damage:*

- Keep connector away from moving parts.
- Do not allow connector to be pinched or trapped.
- Protect connector from rough or sharp edges (such as hole in side of cabinet) that could wear away hose surface over time which may lead to water damage.

