


44224, 44229, 44824, 44829

Boraam

Boraam Industries


BACKLESS SWIVEL STOOL

ASSEMBLY INSTRUCTIONS






16 PCS




20 PCS



4 PCS




16 PCS




1 PC


1




2







3



4





01



DO NOT TIGHTEN BOLT COMPLETELY.

02



TIGHTEN BOLT COMPLETELY.

4X

03

B




4 PCS


C



4 PCS



TIGHTEN BOLT COMPLETELY.



BE SURE TO CHECK ALL BOLTS ARE SECURELY
TIGHTENED PRIOR USING THIS STOOL.