



A U.S. BLOCK WINDOWS COMPANY

## CARE & CLEANING INSTRUCTIONS

**Clean with a solution of  
MILD SOAP (LIQUID DISH DETERGENT) AND WARM WATER  
ONLY!**

Use a soft, clean cloth with light pressure to remove dust and dirt. Rinse with clean water and dry by blotting with a cloth or chamois.

**Grease, Oil, Tar and Uncured Paint can be removed using MV&P Naptha or Kerosene on a soft cloth. Afterward, clean window using instructions above to remove residue.**

### **DO NOT USE:**

**GASOLINE  
ALCOHOL  
ACETONE  
BENZENE  
TOLUENE  
MINERAL SPIRITS  
PAINT THINNER  
LACQUER THINNER**

If dusting is necessary, use a damp, soft cloth to prevent scratching and static build up on the blocks.

**DO NOT USE "After Shower Sprays,"  
Window or Glass Cleaners, Abrasive or Scouring Cleaners**

**DO NOT USE Squeegees, Scouring Pads, Razor Blades,  
Scrapers or Other Sharp Instruments**

**DO NOT Pressure Wash, Acid Wash or Steam Clean the window**

### **LEAVE THE BUBBLE WRAP ON!**

The window is shipped with bubble wrap on both sides to protect the blocks. The wrap can be peeled back to inspect for damage, but should be replaced to protect the window from scratches, mortar and overspray during construction. Once construction is complete, the bubble wrap can be removed.

**FAILURE TO FOLLOW ALL OF THE ABOVE INSTRUCTIONS  
VOIDS ALL WARRANTIES**

SCRATCH REMOVAL AND BLOCK REPLACEMENT KITS ARE AVAILABLE