## **PACKING PROCESS**

22SV23269 (5125184) Hovering Witch


## **READ AND SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE**



## **PARTS LIST**

- A. Right Base Half x 1
  B. Left Base Half x 1
  C. Lower Support Pole x 1
  D. Broom Bristles x 1
- Support Pole x 1
- F. Broom Stick Bottom x 1 G. Broom Stick Middle x 1
- H. Broom Stick Upper x1
- I. Upper Support Pole x 1
  J. Broom Stick Cap x 1
  K. Right Arm x 1

- L. Right Hand x 1 M. Costume x 1
- N. Upper Torso Frame x 1
  O. Lower Torso Frame x 1
- P. Head x 1
- Q. Hip Hoop x 1
  R. Leg Frames x 2
  S. Foam Tubes x 2
- T. Left Arm x 1 U. Left Hand x 1
- V. Cape x 1 W. Hat x 1
- X. Broomstick Top x 1 Y. Base Extensions x 4
- Z. Adapter Reciever x 1 Z1. Elastic Band x 1
- Z2. Stakes x 4 Z3. Adapter \* x 1





1. Place the small cardboard insert in the bottom right corner of the box. Then slide the (W) Hat into the provided plastic bag and then place the (W)Hat in the middle of the box.



2. Place the (P) Head into the provided plastic bag and then place the (L) Right Hand, (P) Head, (U) Left Hand, and (Z) Adapter into the box shown in Figure 2.



3. Place the small box with the (L P, U, Z) Parts into the larger box so that it makes contact with the back and right interior walls. Make sure the smaller box is oriented with the longer side contacting the right interior of the box.



4. Place the (K) Right Arm, (O) Lower Torso Frame, (Q) Hip Hoop, (Z2) Stakes, and (Z3) Adapter into the small box shown in Figure 4.



5. Place the cardboard insert into the box so that the long surface of the insert makes contact with the left interior wall of the box. Then place the small box with the (K, O, Z2, Z3) Parts into the box so that the small box makes contact with the back interior wall of the box. Make sure the box is oriented as shown in Figure 5.



6. Place the shoulder area of the (N) Upper Torso Frame into the cardboard insert in the box. Aim the metal frame of the (N) Upper Torso Frame towards the center of the box. Make sure the (N) Upper Torso Frame is oriented as it is shown in Figure 6.



7. Put the (M) Costume and (V) Cape into their provided plastic bags and place into the front area of the box over the (W) Hat.



8. Place the (D) Broom Bristles into its provided plastic bag and place on top of the (M, V) Costume components.



9. Place the (F) Broom Stick Bottom, (G) Broom Stick Middle, (H) Broom Stick Upper, (J) Broom Stick Cap, and (X) Broom Stick Top into the front area of the box over the (D) Broom Bristles. Then place the (S) Foam Tubes folded up over the small box with the (K, O, Q, Z2, Z3) Parts.



10. Place the (T) Left Arm over the (S) Foam Tubes. Make sure the (T) Left Arm is oriented as shown in Figure 10.



11. Place the (R) Leg Frames with the (Z1) Elastic Band attached into the box so that the connection point of the (R) Leg Frames is placed inside of the box insert.



12. Place the (A) Right Base Half into the box so that the connection points that attach to the (B) Left Base Half are aimed towards the back of the box. Make sure the pole of the (A) Right Base Half is aimed downward into the box.



13. Place the flat cardboard insert into the box over all parts. Make sure the cardboard insert is oriented as shown in Figure 13.



14. Place the (B) Left Base Half into the box so that it makes contact with the back interior wall of the box and that the (Y) Base Extension connection points of the (B) Left Base Half are aimed at each back corner. Place the (Y) Base Extensions under the (B) Left Base Half. The place the (C) Lower Support Pole and the (I) Upper Support Pole together in the front area of the box. Make sure the pole coming off of the (I) Upper Support Pole is aimed downward into the cardboard insert. Then place the (E) Support Pole in the box so that it makes contact with the front interior wall of the box.



15. Close the lid and seal the box with tape. Your Hovering Witch is now fully packed. Store away from heat and moisture.