

**GOO
GONE.**

**PRO-POWER
GOO & ADHESIVE REMOVER**

Goo Gone® Pro-Power combines the power of citrus oils from oranges with a blend of refined oils to defeat the toughest goos. Removes adhesive, sealants, tree sap, wet paint, glue, grease & grime, asphalt, ink, marker, soot, tar, wax, oil and more.

SURFACE SAFE



TOOLS



HARD SURFACES



CARPET



CLOTHING

Do Not Use On: Silk, leather, suede, rubber, faux stainless steel, unpainted drywall, unfinished wood surfaces, and unsealed stone

No utilizar sobre superficies de seda, cuero, ante, caucho, acero inoxidable de imitación, cartón yeso sin pintar, madera sin acabado ni piedra no sellada

**Para obtener las traducciones en español, visite gooone.com*

Directions: Pre-test on an inconspicuous area. **Hard Surfaces:** 1. Apply Goo Gone. 2. Wipe. 3. Wash with hot soapy water. For extra gooeey messes let sit 5-10 minutes. **Clothing:** Do not treat clothing while wearing. 1. Apply Goo Gone to stain. 2. Blot with clean white cloth. 3. Launder separately using extra detergent. **Carpet:** 1. Apply Goo Gone to clean white cloth. 2. Gently blot stain. 3. Clean area with soap and water. USE ONLY PER LABEL DIRECTIONS.

DANGER: HARMFUL OR FATAL IF SWALLOWED. Do not swallow. Do not get in eyes or on skin or clothing. Do not breathe fumes. **KEEP OUT OF REACH OF CHILDREN.** Wear appropriate protection to ensure product does not get on eyes or skin. Use only in a well-ventilated area. Contains: petroleum distillates. **FIRST AID TREATMENT:** If swallowed, call a Poison Control Centre or doctor immediately. Do not induce vomiting. If in eyes or on skin, rinse well with water. If on clothes, remove clothes. If breathed in, move person into fresh air.

Phosphate Free.

MADE IN THE USA



With US and imported parts



CC Holdings, Inc. | 755 Tri-State Parkway | Gurnee, IL 60031
GooGone.com | 855.364.8135