

DB2604

The ultimate upgrade made from Silicon Nitride, robust and durable. This direct drop in upgrade replaces Pentair 472604 NT TSI & STD

- 3 year warranty
- Simple to fit
- Direct drop in replacement
- Used in following
- Replaces the following Part Number; Pentair 472604 NT TSI & STD

Replaces
Pentair 472604 NT TSI & STD

Used In
Pentair Models
H250IDL2
H350IDL2
H450IDL2



Warranty

Direct Brand will, during the period of warranty from the date of purchase, replace the igniter, free of charge, where it is faulty due to defective materials or workmanship.

This warranty is only valid in the United States of America and Canada, 3 years from date of purchase, and on production of the original sales receipt or invoice together with the faulty product.

You may not claim under this warranty when the igniter is damaged as a result of accident, commercial use, fair wear and tear or misuse (including, without limitation failure to use the igniter for its normal purpose, in accordance with the instructions or use in a manner inconsistent with applicable local technical or safety standards).

Any adaptation or adjustment to, or alteration of, the igniter carried out for any reason, whether properly carried out or not. Where permitted under applicable law, this warranty will be your sole and exclusive remedy for breach of any warranty, guarantee or condition, express or implied, in respect of this product and neither Direct Brand nor their suppliers will be liable for any incidental or consequential loss or damage.