



# Max Strip Floor Adhesive Remover

## Technical Data Sheet

- ✓ Strip adhesives & mastics from multiple surfaces.
- ✓ The DIY friendly glue remover that works.
- ✓ Generates start to finish add on sales throughout your stores.
- ✓ Low VOC no drip easy to use gel formula.
- ✓ Indoor safe great for all year-round projects.

## Description

Max Strip Floor adhesive remover is a water-based/water soluble remover. Suitable for; all woods, metals (including aluminum), concrete, stone, brick, and other hard surfaces. Max Strip Floor Adhesive Remover is designed to remove all kinds of adhesives including most construction glues from surfaces safely, and completely dust free removal process. Caution: may etch some plastics, always test a small area first for surface integrity, not designed to remove factory finished, heat treated, or baked on coatings.

## Physical Properties

This 100% cling gel has a low odor. Gel is easily cleaned up with just water. Product is white in color to ensure even application.

## Typical Performance

Minimum set time 30 minutes.

Heavy duty or thicker adhesives can take 1- 3 hours or longer.

**The above times are approximations and subject to substrate, age, type of coating, and layers of coating.**

If possible, always test a small area first for optimal removal time. Coverage is approximately 30 – 50 sq ft per litre.

## Environmental

All materials are readily biodegradable & water soluble. Care must be taken to ensure that any removed solids do not enter surface water drains during removal projects. Disposal of this product or any by-products should always comply with the requirements of the Environmental Protection Act and its subsidiary regulations and any regional Local Authority requirements. Max Strip products are safe to dispose of in your household garbage.

# Instructions for Use

Before you start: \*For best performance use MAX Strip above 10°C (50°F). Do not use in direct sunlight. Do not freeze.



Shake well before use. Apply formula with a paint brush. For large areas pour onto the surface and spread with a long-handled paint roller for even application.



Set times will vary, allow the formula time to saturate problem areas as needed.

Minimum set time 30 minutes. Heavy duty or thicker adhesives can take 1- 3 hours or longer.



For floors use a long-handled sidewalk scraper or floor hoe to scrape softened material. For hard surfaces, scrape with the appropriate tool when ready. Scrub any remaining material with a stiff bristle brush and water before the surface dries out. For carpet and clothing gently scrub problem areas.



Clean the treated surface with mild soap and water. Repeat steps if necessary.