


ASSEMBLY INSTRUCTIONS










10 x1 	11 x1 	12 x1
13 x1 	14 x1 	15 x2
16 x1 	17 x2 	18 x4
19 x1 	20 x2 	21 x1
22 x1 		


PARTS LIST

1 x4 	2 x1 	3 x1
4 x1 	5 x2 	6 x1
7 x1 	8 x1 	9 x2

ASSEMBLY INSTRUCTIONS

HARDWARE LIST


A x12 	B x4 
1/4 X 1/2	4.0 X 25
C x16 	D x28 
1/4 X 1-1/8	3.5 X 20
E x6 	F x6 
G x4 	H x2 
M4 X 6	M4 X 28
I x2 	J x2 
3.0 X 12	
K x2 	L x4 
M x1 	




When the process of product assembly, please do not lock the screws at one time, but wait until all the screws are assembled to the position, and then straighten and flatten the product, and then tighten the screws of the same height in turn, so as to avoid unsmooth assembly and product tilt.

ASSEMBLY INSTRUCTIONS


STEP 1



STEP 2



STEP 3




ASSEMBLY INSTRUCTIONS


STEP 4





x 2



STEP 5




STEP 6




ASSEMBLY INSTRUCTIONS


STEP 7




x2



STEP 9




x2



STEP 8


x2



STEP 10




x2



ASSEMBLY INSTRUCTIONS


STEP 11

 D x 6




STEP 13

 E x 6




STEP 12

 D x 6




STEP 14

 F x 6





ASSEMBLY INSTRUCTIONS


STEP 15



STEP 17




STEP 16





ASSEMBLY INSTRUCTIONS

STEP 18




STEP 19





ASSEMBLY INSTRUCTIONS

STEP 20




STEP 21




ASSEMBLY INSTRUCTIONS

STEP 22




STEP 23



ASSEMBLY INSTRUCTIONS

STEP 24



STEP 25

