SAFETY DATA SHEET



1. Identification

Product identifier Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss

Other means of identification

Product code B000444

Recommended use **Architectural Coating**

Recommended restrictions None known.

Manufacturer/Importer/Supplier/Distributor information

Supplier Behr Process Corp.

> 1801 E. St. Andrew Place Santa Ana. CA 92705

Telephone 714-545-7101

Emergency telephone

number

(800)-424-9300 CHEMTREC®

2. Hazard(s) identification

Physical hazards Flammable aerosols Category 1

> Gases under pressure Compressed gas

Health hazards Skin corrosion/irritation Category 2

> Serious eye damage/eye irritation Category 2A Sensitization, skin Category 1 Carcinogenicity Category 2 Reproductive toxicity Category 2

Specific target organ toxicity, single exposure Category 3 narcotic effects

Specific target organ toxicity, repeated

exposure

Category 2 (central nervous system)

OSHA defined hazards Not classified.

Label elements



Signal word Danger

Hazard statement Extremely flammable aerosol. Contains gas under pressure; may explode if heated. Causes skin

> irritation. May cause an allergic skin reaction. Causes serious eve irritation. May cause drowsiness or dizziness. Suspected of causing cancer. Suspected of damaging fertility or the unborn child. May cause damage to organs (central nervous system) through prolonged or

repeated exposure.

Precautionary statement

Storage

Obtain special instructions before use. Do not handle until all safety precautions have been read Prevention

> and understood. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Do not spray on an open flame or other ignition source. Pressurized container: Do not pierce or burn, even after use. Do not breathe mist/vapors. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Contaminated work clothing must not be allowed out of the workplace.

Wear protective gloves/protective clothing/eye protection/face protection.

If on skin: Wash with plenty of water. Take off contaminated clothing and wash it before reuse. If Response skin irritation or rash occurs: Get medical advice/attention. If inhaled: Remove person to fresh air

and keep comfortable for breathing. If exposed or concerned: Get medical advice/attention. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy

to do. Continue rinsing. If eye irritation persists: Get medical advice/attention.

Store in a well-ventilated place. Keep container tightly closed. Store locked up. Protect from

sunlight. Do not expose to temperatures exceeding 50°C/122°F.

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss

SDS US 950443 Version #: 1.0 Revision date: 8-9-19 Issue date: 8-9-19

Disposal

Hazard(s) not otherwise classified (HNOC)

Dispose of contents/container in accordance with local/regional/national/international regulations.

None known.

Supplemental information

None.

3. Composition/information on ingredients

Mixtures

Chemical name	CAS number	%	
Acetone	67-64-1	10 - 20	
Propane	74-98-6	10 - 20	
n-Butyl acetate	123-86-4	10 - 20	
2-Methoxy-1-methylethyl acetate	108-65-6	2.5 - 10	
Isobutane	75-28-5	2.5 - 10	
Isobutyl acetate	110-19-0	2.5 - 10	
Xylene	1330-20-7	2.5 - 10	
Petroleum ether	8032-32-4	1 - 2.5	
Titanium dioxide	13463-67-7	1 - 2.5	
2-Butanone oxime	96-29-7	0.1 - 1	
Toluene	108-88-3	0.1 - 1	

Composition comments

The manufacturer has claimed the exact percentage as trade secret under the OSHA Hazard Communication Standard.

4. First-aid measures

Inhalation

Remove victim to fresh air and keep at rest in a position comfortable for breathing. Call a poison center or doctor/physician if you feel unwell.

Skin contact

Remove contaminated clothing immediately and wash skin with soap and water. In case of eczema or other skin disorders: Seek medical attention and take along these instructions. Wash contaminated clothing before reuse.

Eye contact

Immediately flush eyes with plenty of water for at least 15 minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Get medical attention if irritation develops and persists.

Ingestion

Not likely, due to the form of the product. In the unlikely event of swallowing contact a physician or poison control center. Rinse mouth.

Most important symptoms/effects, acute and delayed

May cause drowsiness and dizziness. Narcosis. Headache. Nausea, vomiting. Behavioral changes. Decrease in motor functions. Severe eye irritation. Symptoms may include stinging, tearing, redness, swelling, and blurred vision. Skin irritation. May cause redness and pain. May cause an allergic skin reaction. Dermatitis. Rash. Prolonged exposure may cause chronic effects. Provide general supportive measures and treat symptomatically. Keep victim under observation.

Indication of immediate medical attention and special treatment needed

Symptoms may be delayed.

General information

IF exposed or concerned: Get medical advice/attention. Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves. Show this safety data sheet to the doctor in attendance. Wash contaminated clothing before reuse.

5. Fire-fighting measures

Suitable extinguishing media
Unsuitable extinguishing
media

Water fog. Alcohol resistant foam. Dry chemical powder. Carbon dioxide (CO2).

Do not use water jet as an extinguisher, as this will spread the fire.

Specific hazards arising from the chemical

Contents under pressure. Pressurized container may explode when exposed to heat or flame. During fire, gases hazardous to health may be formed.

Special protective equipment and precautions for firefighters

Firefighters must use standard protective equipment including flame retardant coat, helmet with face shield, gloves, rubber boots, and in enclosed spaces, SCBA.

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss

950443 Version #: 1.0 Revision date: 8-9-19 Issue date: 8-9-19

2 / 11

Fire fighting Specific methods

equipment/instructions

Move containers from fire area if you can do so without risk. Containers should be cooled with water to prevent vapor pressure build up.

Use standard firefighting procedures and consider the hazards of other involved materials. Move containers from fire area if you can do so without risk.

General fire hazards

Extremely flammable aerosol. Contents under pressure. Pressurized container may explode when exposed to heat or flame.

6. Accidental release measures

Personal precautions. protective equipment and emergency procedures

Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Keep out of low areas. Many gases are heavier than air and will spread along ground and collect in low or confined areas (sewers, basements, tanks). Wear appropriate protective equipment and clothing during clean-up. Do not breathe mist/vapors. Emergency personnel need self-contained breathing equipment. Do not touch damaged containers or spilled material unless wearing appropriate protective clothing. Ventilate closed spaces before entering them. Local authorities should be advised if significant spillages cannot be contained. For personal protection, see section 8 of the SDS.

Methods and materials for containment and cleaning up Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area). Keep combustibles (wood, paper, oil, etc.) away from spilled material. Stop the flow of material, if this is without risk. For waste disposal, see section 13 of the SDS.

Environmental precautions

Avoid discharge into drains, water courses or onto the ground.

7. Handling and storage

Precautions for safe handling

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Pressurized container: Do not pierce or burn, even after use. Do not use if spray button is missing or defective. Do not spray on a naked flame or any other incandescent material. Do not smoke while using or until sprayed surface is thoroughly dry. Do not cut, weld, solder, drill, grind, or expose containers to heat, flame, sparks, or other sources of ignition. Do not breathe mist/vapors. Avoid contact with eyes, skin, and clothing. Avoid prolonged exposure. Pregnant or breastfeeding women must not handle this product. Use only in well-ventilated areas. Wear appropriate personal protective equipment. Observe good industrial hygiene practices.

Conditions for safe storage, including any incompatibilities Store locked up. Pressurized container. Protect from sunlight and do not expose to temperatures exceeding 50°C/122 °F. Do not puncture, incinerate or crush. Do not handle or store near an open flame, heat or other sources of ignition. Store in a well-ventilated place. Stored containers should be periodically checked for general condition and leakage. Store away from incompatible materials (see Section 10 of the SDS).

8. Exposure controls/personal protection

Occupational exposure limits

Components	Туре	Value	Form
Acetone (CAS 67-64-1)	PEL	2400 mg/m3	
		1000 ppm	
Isobutyl acetate (CAS 110-19-0)	PEL	700 mg/m3	
ŕ		150 ppm	
n-Butyl acetate (CAS 123-86-4)	PEL	710 mg/m3	
		150 ppm	
Propane (CAS 74-98-6)	PEL	1800 mg/m3	
		1000 ppm	
Titanium dioxide (CAS 13463-67-7)	PEL	15 mg/m3	Total dust.
Xylene (CAS 1330-20-7)	PEL	435 mg/m3	
		100 ppm	
US. OSHA Table Z-2 (29 CFR 191	0.1000)		
Components	Туре	Value	
Toluene (CAS 108-88-3)	Ceiling	300 ppm	
	TWA	200 ppm	

Issue date: 8-9-19

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss 950443 Version #: 1.0 Revision date: 8-9-19

SDS US

3 / 11

US. OSHA Table Z-3 (29 CFR 191 Components	Type	Value	Form
Titanium dioxide (CAS 13463-67-7)	TWA	5 mg/m3	Respirable fraction.
0400-01-1)		15 mg/m3	Total dust.
		50 mppcf	Total dust.
		15 mppcf	Respirable fraction.
IS. ACGIH Threshold Limit Value	es		
components	Type	Value	
cetone (CAS 67-64-1)	STEL	500 ppm	
	TWA	250 ppm	
obutane (CAS 75-28-5)	STEL	1000 ppm	
obutyl acetate (CAS 10-19-0)	STEL	150 ppm	
	TWA	50 ppm	
-Butyl acetate (CAS 23-86-4)	STEL	150 ppm	
	TWA	50 ppm	
itanium dioxide (CAS 3463-67-7)	TWA	10 mg/m3	
oluene (CAS 108-88-3)	TWA	20 ppm	
ylene (CAS 1330-20-7)	STEL	150 ppm	
	TWA	100 ppm	
S. NIOSH: Pocket Guide to Che	mical Hazards		
omponents	Туре	Value	
cetone (CAS 67-64-1)	TWA	590 mg/m3	
		250 ppm	
obutane (CAS 75-28-5)	TWA	1900 mg/m3	
		800 ppm	
obutyl acetate (CAS 10-19-0)	TWA	700 mg/m3	
		150 ppm	
n-Butyl acetate (CAS 123-86-4)	STEL	950 mg/m3	
		200 ppm	
	TWA	710 mg/m3	
		150 ppm	
etroleum ether (CAS 032-32-4)	Ceiling	1800 mg/m3	
	TWA	350 mg/m3	
ropane (CAS 74-98-6)	TWA	1800 mg/m3	
		1000 ppm	
Toluene (CAS 108-88-3)	STEL	560 mg/m3	
		150 ppm	
	TWA	375 mg/m3	
		100 ppm	
(l (OAO 4000 00 7)	OTEL		

Xylene (CAS 1330-20-7)

STEL

655 mg/m3

150 ppm

96-29-7)

10 ppm

2-Methoxy-1-methylethyl
acetate (CAS 108-65-6)

TWA
50 ppm

Biological limit values

ACGIH Biological Exposure Indices

Components	Value	Determinant	Specimen	Sampling Time
Acetone (CAS 67-64-1)	25 mg/l	Acetone	Urine	*
Toluene (CAS 108-88-3)	0.3 mg/g	o-Cresol, with hydrolysis	Creatinine in urine	*
	0.03 mg/l	Toluene	Urine	*
	0.02 mg/l	Toluene	Blood	*
Xylene (CAS 1330-20-7)	1.5 g/g	Methylhippuric acids	Creatinine in urine	*

^{* -} For sampling details, please see the source document.

Exposure guidelines

US - California OELs: Skin designation

2-Methoxy-1-methylethyl acetate (CAS 108-65-6)

Can be absorbed through the skin.

Can be absorbed through the skin.

Can be absorbed through the skin.

US - Minnesota Haz Subs: Skin designation applies

Toluene (CAS 108-88-3) Skin designation applies.

Appropriate engineering

controls

Good general ventilation should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. Provide eyewash station and safety shower.

Individual protection measures, such as personal protective equipment

Eye/face protection Wear safety glasses with side shields (or goggles).

Skin protection

Hand protection Wear appropriate chemical resistant gloves.

Skin protection

Other Wear appropriate chemical resistant clothing. Use of an impervious apron is recommended.

Respiratory protection If airborne concentrations are above the applicable exposure limits, use NIOSH approved

respiratory protection. Chemical respirator with organic vapor cartridge and full facepiece. Use a positive-pressure air-supplied respirator if there is any potential for an uncontrolled release, exposure levels are not known, or any other circumstances where air-purifying respirators may not

provide adequate protection.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

Observe any medical surveillance requirements. When using do not smoke. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants. Contaminated work clothing should not be allowed out of the workplace.

9. Physical and chemical properties

Appearance

Physical state Liquid.
Form Aerosol.

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss

950443 Version #: 1.0 Revision date: 8-9-19 Issue date: 8-9-19

5 / 11

ColorNot available.OdorNot available.Odor thresholdNot available.pHNot available.

Melting point/freezing point Initial boiling point and boiling

247.9 °F (120 °C) estimated

Not available.

range

Flash point -155.9 °F (-104.4 °C) Propellant estimated

Evaporation rate Not available.

Flammability (solid, gas) Not applicable.

Upper/lower flammability or explosive limits

Flammability limit - lower

1.6 % estimated

(%)

Flammability limit - upper

9.3 % estimated

(%)

Vapor pressure 60 - 70 psig (68 °F (20 °C)) estimated

Vapor density Not available.

Relative density Not available.

Solubility(ies)

Solubility (water) Not available.

Partition coefficient Not available.

(n-octanol/water)

Auto-ignition temperature 827.1 °F (441.72 °C) estimated

Decomposition temperature Not available. **Viscosity** Not available.

Other information

Explosive properties Not explosive.

Flammability class Flammable IB estimated
Heat of combustion 25.65 kJ/g estimated

Oxidizing properties Not oxidizing.

VOC MIR <0.95

10. Stability and reactivity

ReactivityThe product is stable and non-reactive under normal conditions of use, storage and transport.

Chemical stability Material is stable under normal conditions.

Possibility of hazardous

reactions

No dangerous reaction known under conditions of normal use.

Conditions to avoid Heat. Avoid temperatures exceeding the flash point. Contact with incompatible materials.

Incompatible materials Strong acids. Strong oxidizing agents. Chlorine. Fluorine. Halogens. Nitrates.

Hazardous decomposition

products

No hazardous decomposition products are known.

11. Toxicological information

Information on likely routes of exposure

Inhalation May cause drowsiness and dizziness. Headache. Nausea, vomiting. Prolonged inhalation may be

harmful.

Skin contact Causes skin irritation. May cause an allergic skin reaction.

Eye contact Causes serious eye irritation.

Ingestion Expected to be a low ingestion hazard.

Symptoms related to the physical, chemical and toxicological characteristics

May cause drowsiness and dizziness. Narcosis. Headache. Nausea, vomiting. Behavioral changes. Decrease in motor functions. Severe eye irritation. Symptoms may include stinging, tearing, redness, swelling, and blurred vision. Skin irritation. May cause redness and pain. May

cause an allergic skin reaction. Dermatitis. Rash.

Information on toxicological effects

Not expected to be acutely toxic.

Test Results Components **Species** 2-Butanone oxime (CAS 96-29-7) **Acute Dermal** LD50 Rabbit > 1000 mg/kg, 24 Hours Oral LD50 Rat > 900 mg/kg 2-Methoxy-1-methylethyl acetate (CAS 108-65-6) **Acute Dermal** LD50 Rabbit > 5000 mg/kg Oral LD50 Rat > 8532 mg/kg Acetone (CAS 67-64-1) **Acute Dermal** LD50 > 15700 mg/kg, 24 Hours Rabbit Inhalation Vapor LC50 Rat 76 mg/l, 4 Hours Oral LD50 Rat 5800 mg/kg Isobutane (CAS 75-28-5) <u>Acute</u> Inhalation LC50 Mouse 52 mg/l, 1 Hours Isobutyl acetate (CAS 110-19-0) **Acute Dermal** LD50 Rabbit > 5000 mg/kg Oral LD50 Rat 13400 mg/kg n-Butyl acetate (CAS 123-86-4) **Acute** Inhalation LC50 Rat 2000 ppm, 4 Hours Oral LD50 Rat 10768 mg/kg Propane (CAS 74-98-6) **Acute** Inhalation Gas LC50 Rat > 80000 ppm, 15 Minutes Titanium dioxide (CAS 13463-67-7) **Acute** Inhalation LC50 Rat 3.43 mg/l, 4 Hours Oral LD50 Rat > 5000 mg/kg

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss SDS US Issue date: 8-9-19

Species Test Results Components

Toluene (CAS 108-88-3)

Acute

Dermal

LD50 Rabbit 12200 mg/kg

Inhalation

Vapor

Rat LC50 28.1 mg/l, 4 Hours

Xylene (CAS 1330-20-7)

Acute Oral

LD50 Rat 3523 mg/kg

Skin corrosion/irritation Causes skin irritation.

Serious eye damage/eye

irritation

Causes serious eye irritation.

Respiratory or skin sensitization

Respiratory sensitization Not a respiratory sensitizer.

May cause an allergic skin reaction. Skin sensitization

Germ cell mutagenicity No data available to indicate product or any components present at greater than 0.1% are

mutagenic or genotoxic.

Carcinogenicity Suspected of causing cancer.

IARC Monographs. Overall Evaluation of Carcinogenicity

Titanium dioxide (CAS 13463-67-7) 2B Possibly carcinogenic to humans.

Toluene (CAS 108-88-3) 3 Not classifiable as to carcinogenicity to humans. Xylene (CAS 1330-20-7) 3 Not classifiable as to carcinogenicity to humans.

NTP Report on Carcinogens

Not listed.

OSHA Specifically Regulated Substances (29 CFR 1910.1001-1053)

Not listed.

Reproductive toxicity Possible reproductive hazard. Components in this product have been shown to cause birth defects

and reproductive disorders in laboratory animals. Suspected of damaging fertility or the unborn

child.

Specific target organ toxicity -

single exposure

May cause drowsiness and dizziness.

Specific target organ toxicity -

repeated exposure

May cause damage to organs (central nervous system) through prolonged or repeated exposure.

Not an aspiration hazard. **Aspiration hazard**

Prolonged inhalation may be harmful. May cause damage to organs through prolonged or **Chronic effects**

repeated exposure. Prolonged exposure may cause chronic effects.

12. Ecological information

Ecotoxicity The product is not classified as environmentally hazardous.

Persistence and degradability

No data is available on the degradability of any ingredients in the mixture.

Bioaccumulative potential

Mobility in soil No data available.

Other adverse effects The product contains volatile organic compounds which have a photochemical ozone creation

potential.

13. Disposal considerations

Disposal instructions Collect and reclaim or dispose in sealed containers at licensed waste disposal site. Contents

under pressure. Do not puncture, incinerate or crush. Dispose of contents/container in accordance

with local/regional/national/international regulations.

Local disposal regulations Dispose in accordance with all applicable regulations.

The waste code should be assigned in discussion between the user, the producer and the waste Hazardous waste code

disposal company.

Waste from residues / unused

products

Dispose of in accordance with local regulations. Empty containers or liners may retain some product residues. This material and its container must be disposed of in a safe manner (see:

Disposal instructions).

Contaminated packaging Since emptied containers may retain product residue, follow label warnings even after container is

emptied. Empty containers should be taken to an approved waste handling site for recycling or

disposal. Do not re-use empty containers.

14. Transport information

DOT

UN number UN1950 UN proper shipping name **AEROSOLS**

Transport hazard class(es)

Class 2.1 Subsidiary risk Label(s) 2.1 Packing group **Environmental hazards**

> Marine pollutant No.

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

N82 **Special provisions** Packaging exceptions 306 Packaging non bulk None Packaging bulk None

IATA

UN1950 **UN number UN proper shipping name** Aerosols

Transport hazard class(es)

2.1 Class Subsidiary risk **Packing group Environmental hazards** Nο **ERG Code** 10L

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

IMDG

UN1950 **UN** number **UN proper shipping name AEROSOLS**

Transport hazard class(es)

Class 2.1 Subsidiary risk Packing group **Environmental hazards**

Marine pollutant No F-D. S-U **EmS**

Special precautions for user Read safety instructions, SDS and emergency procedures before handling. Not established.

Transport in bulk according to Annex II of MARPOL 73/78 and

the IBC Code

15. Regulatory information

US federal regulations This product is a "Hazardous Chemical" as defined by the OSHA Hazard Communication

Standard, 29 CFR 1910.1200.

All components are listed on or exempt from the U.S. EPA TSCA Inventory List.

TSCA Section 12(b) Export Notification (40 CFR 707, Subpt. D)

Not regulated.

CERCLA Hazardous Substance List (40 CFR 302.4)

Acetone (CAS 67-64-1) Listed. Isobutane (CAS 75-28-5) Listed. Isobutyl acetate (CAS 110-19-0) Listed. n-Butyl acetate (CAS 123-86-4) Listed. Propane (CAS 74-98-6) Listed. Toluene (CAS 108-88-3) Listed.

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss

Xylene (CAS 1330-20-7)

Listed.

SARA 304 Emergency release notification

Not regulated.

OSHA Specifically Regulated Substances (29 CFR 1910.1001-1053)

Toxic Substances Control Act (TSCA)

Superfund Amendments and Reauthorization Act of 1986 (SARA)

SARA 302 Extremely hazardous substance

Not listed.

SARA 311/312 Hazardous

Yes

chemical

Classified hazard categories

Flammable (gases, aerosols, liquids, or solids)

Gas under pressure

Skin corrosion or irritation

Serious eve damage or eve irritation Respiratory or skin sensitization

Carcinogenicity Reproductive toxicity

Specific target organ toxicity (single or repeated exposure)

SARA 313 (TRI reporting)

Chemical name	CAS number	% by wt.	
Toluene	108-88-3	0.1 - 1	
Xylene	1330-20-7	2.5 - 10	

Other federal regulations

Clean Air Act (CAA) Section 112 Hazardous Air Pollutants (HAPs) List

Toluene (CAS 108-88-3) Xylene (CAS 1330-20-7)

Clean Air Act (CAA) Section 112(r) Accidental Release Prevention (40 CFR 68.130)

Isobutane (CAS 75-28-5) Propane (CAS 74-98-6)

Safe Drinking Water Act

Not regulated.

(SDWA)

Drug Enforcement Administration (DEA). List 2, Essential Chemicals (21 CFR 1310.02(b) and 1310.04(f)(2) and **Chemical Code Number**

Acetone (CAS 67-64-1) 6532 Toluene (CAS 108-88-3) 6594

Drug Enforcement Administration (DEA). List 1 & 2 Exempt Chemical Mixtures (21 CFR 1310.12(c))

Acetone (CAS 67-64-1) 35 %WV Toluene (CAS 108-88-3) 35 %WV

DEA Exempt Chemical Mixtures Code Number

Acetone (CAS 67-64-1) 6532 Toluene (CAS 108-88-3) 594

FEMA Priority Substances Respiratory Health and Safety in the Flavor Manufacturing Workplace

Acetone (CAS 67-64-1) Low priority Isobutyl acetate (CAS 110-19-0) Low priority n-Butyl acetate (CAS 123-86-4) Low priority

US state regulations

US. Massachusetts RTK - Substance List

Acetone (CAS 67-64-1) Isobutane (CAS 75-28-5) Isobutyl acetate (CAS 110-19-0) n-Butyl acetate (CAS 123-86-4) Propane (CAS 74-98-6)

Titanium dioxide (CAS 13463-67-7)

Toluene (CAS 108-88-3) Xylene (CAS 1330-20-7)

US. New Jersey Worker and Community Right-to-Know Act

Acetone (CAS 67-64-1) Isobutane (CAS 75-28-5)

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss 950443 Version #: 1.0 Revision date: 8-9-19 10 / 11 Issue date: 8-9-19

SDS US

Isobutyl acetate (CAS 110-19-0) n-Butyl acetate (CAS 123-86-4) Petroleum ether (CAS 8032-32-4)

Propane (CAS 74-98-6)

Titanium dioxide (CAS 13463-67-7)

Toluene (CAS 108-88-3) Xylene (CAS 1330-20-7)

US. Pennsylvania Worker and Community Right-to-Know Law

Acetone (CAS 67-64-1) Isobutane (CAS 75-28-5) Isobutyl acetate (CAS 110-19-0) n-Butyl acetate (CAS 123-86-4) Petroleum ether (CAS 8032-32-4)

Propane (CAS 74-98-6)

Titanium dioxide (CAS 13463-67-7)

Toluene (CAS 108-88-3) Xylene (CAS 1330-20-7)

US. Rhode Island RTK

Acetone (CAS 67-64-1)

Isobutyl acetate (CAS 110-19-0) n-Butyl acetate (CAS 123-86-4)

Propane (CAS 74-98-6)

Titanium dioxide (CAS 13463-67-7)

Toluene (CAS 108-88-3) Xylene (CAS 1330-20-7)

16. Other information, including date of preparation or last revision

Issue date August 9, 2019
Revision date August 9, 2019

Version # 1.0

HMIS® ratings Health: 2*

Flammability: 4 Physical hazard: 3

Disclaimer Behr Process Corp cannot anticipate all conditions under which this information and its product, or

the products of other manufacturers in combination with its product, may be used. It is the user's responsibility to ensure safe conditions for handling, storage and disposal of the product, and to assume liability for loss, injury, damage or expense due to improper use. The information in the

sheet was written based on the best knowledge and experience currently available.

Behr Aerosol Paint + Primer - Hidden Sea Glass Gloss

950443 Version #: 1.0 Revision date: 8-9-19 Issue date: 8-9-19 11 / 11