





HOW TO USE FIRE BLOCK

Always wear eye protection, gloves, and proper work clothing when using foam. Cured foam is difficult to remove from skin, clothing and other substrates.



1. For optimum performance shake can intermittently during extended use. Application temperature is between 23°F and 95°F. Can temperature must be between 41°F and 86°F.
2. Make sure surface is clean and free from dirt, dust, and other substances. Cover surfaces not intended to be foamed.
3. Dispense foam sparingly: Fill void by one-third to avoid overflows.
4. Mist with water to speed cure.
5. Clean spills immediately with acetone. Refer to TDS for detailed instructions.



Say Yes to

LOCTITE

**FIRE BLOCK
FOAM**