

6021-10159 2-Tier Garment Rack





B 1 ea
Top hanging bar

C 1 ea Bottom hanging bar



Bottom vertical tubes

E 2 ea Horizontal base tubes



F 2 ea



G 2 ea Corner connectors

H 2 ea

Middle connectors



l 2 ea Locking wheels




J 2 ea

| Part | Reference |
|------|-----------|
| Α | F10877 |
| В | F10878 |
| С | F10879 |
| D | F10876 |
| Е | F10880 |
| F | F10881 |
| G | F10882 |
| Н | F10883 |
| I | F10257 |
| J | F10258 |

Tools Needed: No tools required.


STEP 1: Assemble the base.

- Insert two horizontal base tubes (E) into two bases (F).




STEP 2: Assemble the bottom hanging bar.

- Insert bottom hanging bar (C) into two middle connectors (H). NOTE: Make sure to press each side in.




STEP 3: Assemble the top hanging bar.

- Insert top hanging bar (B) into two corner connectors (G). NOTE: Make sure to press each side in.



STEP 4a: Assemble rack.

- Insert two bottom vertical tubes (D) into the assembled base.




©2020 Whitmor, Inc. Page 1

6021-10159 2-Tier Garment Rack




STEP 4b: Assemble rack.

- Attach bottom hanging bar and middle connectors **(C+H)** to the bottom vertical tubes **(D)**.
- Place push button side of top vertical tubes **(A)** into the unit until push button clicks into hole.




STEP 5: Attach wheels.

- Attach two locking wheels (I) and two wheels (J) to the bottom as shown.



STEP 4c: Assemble rack.

- Attach top hanging bar and corner connectors (**B+G**) to the top vertical tubes (**A**).



8680 Swinnea Road • Suite 103 • Southaven, MS • 38671

NEED HELP? For help with assembly, or if you are missing a part, please call Whitmor's Consumer Care Team, 1-888-944-8667 between 8 a.m. and 4:30 p.m. (Central Standard Time) Monday through Friday. Or email: help@whitmor.com. Visit us online at www.whitmor.com

Rev#0 10.28.20 Printed in Taiwan

©2020 Whitmor, Inc. Page 2