

INSTRUCTIONS

Cleans surface of loose rotted wood and debris. Remove rotted wood as necessary to allow for maximum penetration.

In a graduated cup, mix equal portions of part A and part B of the J-B Wood Restore Liquid Epoxy. Apply to surface area generously. For an even thickness coat the work surface must be level.

Apply a second coat if necessary.

For rotted wood applications, once fully cured apply J-B Weld Wood Restore Repair Putty or Wood Repair Compound to fill all gaps and surface areas.