




Parts List

M-2000 Series Yard Hydrant



Part No.	Part Description
P-1	Head Casting
P-2	Head Plug
P-10	Lever Casting
P-15	Lever Bolt
G-20	Draw Straps (Per Pair)
G-25	Pivot Connector & Nuts
G-30	Packing Nut
OR110	O-Ring
G-35	Valve Stem Packing
P-40	Valve Body
G-45	Stainless Steel Rod
P-50	Steel Rod Connector
P-60	1" Galvanized Pipe
P-56	3/8" Operating Rod
P-115	Plunger
P-120	Head Assembly Parts No. P-1, P-2, P-10, P-15, P-50, G-20, G-25, G-30, G-35, G-45, OR110